


DUNAVOX FLOW-17H


DAUF-17.58DBH




If the wine cooler is installed within a fully enclosed cabinet, it is essential to ensure proper ventilation from the sides. To achieve this, avoid completely sealing the sides of the cabinet.



Front View



Side View



Top View

